


WN 054306  
05/01




Fitting Instructions

**!** Failure to fit this intumescent gasket invalidates the results obtained in fire resistance tests of timber doorsets including the ITS 96.

This closer is only suitable for half hour fire-rated timber doorsets when fitted with this intumescent gasket set, according to these instructions. (An upgrade kit is available to meet one hour requirements.)

The length and width of mortice for the body must be increased by 2 mm to accommodate the gasket.

Wrap the intumescent gasket around the closer and insert carefully into the prepared mortise.



**!** For fire doors ensure that HOLD OPEN device has been REMOVED from the slide channel.

The mortice for the slide channel must be enlarged by 2 mm in both length and width to accommodate the gasket.

Wrap the intumescent gasket around the slide channel and insert carefully into the prepared mortise.

Subject to change without notice